# **APPENDIX L** LIFT STATION FIELD EVALUATIONS

THIS PAGE INTENTIONALLY LEFT BLANK

Bonney Lake Lift Station Notes – Following list station observation conducted on 06/14/2016

General Notes:

- City would prefer load stacks on generators
- Stations do not have force main isolation valves
- City prefers pressure transducers with float backups

<u>LS 1</u> – 18215-A 95<sup>th</sup> Loop St. E.

- Piping in valve vault very close to floor
- Small grease mat in wet-well
- No general issues or odor issues








#### <u>LS 2</u> – 9914 176<sup>th</sup> Ave. E.

- No general issues or odor issues
- This station is not equipped with the cities standard "Flygt" pumps
- Future development coming to this station
- Bioxide present at station







## <u>LS 3</u> – 18704 82<sup>nd</sup> St. E.

- No general issues or odor issues
- Station services a school
- Handles a large amount of grease from the school










## <u>LS 4</u> – 18308 77<sup>th</sup> St. E.

• No general issues or odor issues







## <u>LS 5</u> – 7002 Myers Road

- No general issues or odor issues
- Very small service area







## <u>LS 6</u> – 18723 A Mcghee Drive

- No general issues or odor issues
- Low flow station
- Pump only has 1400 hours from the last 31 years







## <u>LS 7</u> – 19307 65<sup>th</sup> St. E.

- No general issues or odor issues
- Low flow station







## <u>LS 8</u> – 6603 185<sup>th</sup> Ave. E.

• No general issues or odor issues







#### <u>LS 9</u> – 9300 225<sup>th</sup> Ave. E.

- Take a further look at future options for this station
- Very shallow wet well
- Long problematic force main leaving this station
- Bioxide present at station but not used
- Floor drain in valve vault does not drain effectively







#### LS 10 – 22609 Connells Prairie Rd.

- No odor issues
- Bioxide present

•

- Minor coating issues in valve vault
  - This station scheduled to be upgraded
    - Two future lift stations to come to this station









## <u>LS 11</u> – 5531 W. Tapps HWY

• No general issues or odor issues







## <u>LS 12</u> – 20601 60<sup>th</sup> St. E.

- No general issues or odor issues
- Twin of station 16








## LS 13 – 20919 Church Lake Drive

- No general issues or odor issues
- Newer pressure transducer







## <u>LS 14</u> – 21002 64<sup>th</sup> St. E.

- No odor issues
- Discharge piping and guide rails showing signs of age and rust
- Force main leaving this station runs over the lake on a bridge alongside water main











## LS 15 – 7418-A Vandermark Road

- No odor issues
- Discharge piping slightly rusty
- Low flow station







## <u>LS 16</u> – 20825 60<sup>th</sup> St. E.

- No general issues or odor issues
- Twin of station 12
- Largely fed by grinder pump stations







#### <u>LS 17</u> – 9301 Angeline Rd.

- Largest lift station
- Buildings present at this station
- No odor issues
- Mulch filters used for odor control
- Bypass port present
- 95% of city's sewer passes through this station
- Old generator (1985) described as a "bomb", was almost replaced but cost of removing generator from building was too high









LS 17 cont. – 9301 Angeline Rd.









#### <u>LS 18</u> – 21301 S.R.-410

- No odor issues
- Coal tar epoxy coating in wet-well coming off of lower walls
- Possible new lift station being put in near here in the future







## LS 19 – Willowbrook (Address not listed on sign)

- No odor issues
- Bioxide present
- Wet-well coating peeling in various locations
- Bypass pumping port at this station







LS 20 – Spring Haven (Address not listed on sign)

- No odor issues
- Coating failures in wet-well and valve vault due to H2S coming from station 9
- Station has an ultrasonic transducer which was installed recently and is already failing







#### <u>LS 21</u> – West Hill Dr.

- No general issues or odor issues
- Charcoal filters used for odor control
- Availability for a third pump
- Pumps at this station were specifically designed for this station
  o Having a spare pump would be useful
- Building present





<u>LS 21 cont.</u> – West Hill Dr.







## LS 22 – Brookfield (Address not listed on sign)

- No general issues or odor issues
- Bioxide present
- Fed largely by grinder pump stations
- Pig port present







## <u>LS 23</u> – 22225 96<sup>th</sup> St. East

• Not yet operational







